

Plan

Defective concrete

802